Installing the ChargePAK B1

1. Switch One Mini off and disconnect from the mains power supply.

2. Open the battery compartment.

3. insert the ChargePAK connector plug into the socket in the compartment. Line up the ridges on the plug with the slots in the socket to ensure correct orientation. Do not force the plug.

4. Insert ChargePAK into the battery compartment, logo side out.

5. Replace the battery cover and connect One Mini to the mains.

6. ChargePAK will begin charging.

   Note: When charging your ChargePAK for the first time or after an extended period of inactivity it is recommended that it is charged for around 24 hours to ensure full battery power. If ChargePAK is in a highly discharged state there may be a slight delay before the battery charging indicator is displayed.